



4H-TECH Short Shifters. Power shifters for quicker and shorter gear changes

Fitting guide for 4H-TECH Z-Shift Short Shifter kit.










Remove cables from ball joints.



Remove metal clip and replace it with our special secure ring (included).



Drill 5mm hole in metal cap on top of the linkage. (drill as far on the edge as possible)


















Remove old leaver and put new short shift in place.







Thighten M8 nut firmly (26Nm) and klick both cable back on ball joints.




Put some grease or sillicone at this point of the roller bearing to make shifting smooth.



Fit black cap to prevent dust.







Fit battery back.

